



www.tal-ko.com

TAL-KO RACING LTD SUNDERLAND ROAD SANDY BEDFORDSHIRE SG19 1QY ENGLAND
 TEL: 01767 682020 FAX: 01767 691622 E-MAIL: info@tal-ko.com

EXTREME TAG 115cc BT 82 ENGINE SERVICE

MAY 2023

PARTS & LABOUR REQUIRED FOR SERVICE

COSTS

1) ENGINE STRIP & REBUILD.....	£ 110.00p
2) REBORE & HONE.....	34.34
3) CRANK STRIP & REBUILD.....	24.61
4) CLUTCH STRIP & REBUILD.....	22.89
	TOTAL £191.84p + vat

PARTS

COSTS

5) EXTREME PISTON COMPLETE.....	86.14
6) OIL SEALS (20 x 35 x 7mm IGN SIDE).....	7.80
7) OIL SEALS (25 x 35 x 7mm CLUTCH SIDE).....	7.80
8) MAIN CRANK BEARINGS (£14.95 x 2).....	29.90
9) BIG END PIN (SPECIAL).....	19.90
10) BIG END CAGE & ROLLERS.....	14.90
11) SMALL END ASSEMBLY COMPLETE with THRUST WASHERS.....	20.75
12) GASKET SET (5).....	8.67
13) 10 TOOTH V SPROCKET.....	39.50
14) SERVICE KIT FOR V CLUTCH (Incs: Shoes, Springs, Washers & Clips)....	108.42
15) PULSE PIPE TO CARB.....	2.95
	PARTS TOTAL £ 343.78p + vat

ENGINE SERVICE TOTAL £ 535.62p + vat

ADDITION PARTS OR WORK THAT MAY BE REQUIRED

COSTS

16) CARB REBUILD INCLUDING FULL K10-WB REPAIR KIT.....	27.26 + vat
17) FULL ENGINE FICHE.....	174.56 + vat
18) FICHE CHECK.....	46.92 + vat
19) RUN IN ENGINE.....	86.98 + vat
20) RUN IN + PRODUCE POWER CURVE.....	145.93 + vat
21) MACHINE HEAD.....	48.65 + vat
22) MACHINE HEAD INCLUDING DOME.....	57.80 + vat
23) MACHINE LINER TOP.....	48.65 + vat
24) HELICOIL REPAIR SPARK PLUG THREAD.....	31.61 + vat
25) HELICOIL 5mm, 6mm or 8mm THREADS.....	16.35 + vat
26) CONNECTING ROD.....	164.50 + vat
27) MAIN BEARING CRANK SHIMS.....	2.80 + vat
28) CLUTCH DRUM.....	58.25 + vat

TAG EXTREME 115cc SERVICE