



www.tal-ko.com

TAL-KO RACING LTD SUNDERLAND ROAD SANDY BEDFORDSHIRE SG19 1QY ENGLAND
TEL: 01767 682020 FAX: 01767 691622 E-MAIL: info@tal-ko.com

EXTREME TAG 115cc BT 82 ENGINE SERVICE

MAY 2019

PARTS & LABOUR REQUIRED FOR SERVICE

COSTS

Table with 2 columns: Description and Cost. Items include Engine Strip & Rebuild, Rebores & Hone, Crank Strip & Rebuild, Clutch Strip & Rebuild, and a Total of £164.25p + vat.

PARTS

COSTS

Table with 2 columns: Description and Cost. Items include Extreme Piston Complete, Oil Seals, Main Crank Bearings, Big End Pin, Big End Cage & Rollers, Small End Assembly, Gasket Set, 10 Tooth V Sprocket, Service Kit, and Pulse Pipe. Total: £307.24p + vat.

ENGINE SERVICE TOTAL £ 471.49p + vat

ADDITION PARTS OR WORK THAT MAY BE REQUIRED

COSTS

Table with 2 columns: Description and Cost. Items include Carb Rebuild, Full Engine FICHE, FICHE Check, Run In Engine, Run In + Produce Power Curve, Machine Head, Machine Head including Dome, Machine Liner Top, Helicoil Repair Spark Plug Thread, Helicoil 5mm, 6mm or 8mm Threads, Connecting Rod, Main Bearing Crank Shims, and Clutch Drum.

TAG EXTREME SERVICE